
From: The Stewards
To: All GT4 Competitors
Re: Appendix 7

Bulletin No: GT4-04
Date: 6 Apr 2024
Time: 15:00

A report has been received from the Chief Timekeeper regarding P1 Groupe Car #43. The report indicated the Driver switch was not functioning during Practice 2.


As it was not possible to assign the lap times achieved to a specific Driver the lap times are not valid. Thus, Car #43 has no recorded times for the session and must start at the back of the grid.



Scot Elkins
Steward – Chairman



Coy Arbour
Steward



Elliot Forbes Robinson
Steward