

---

**From:** The Stewards  
**To:** All GT4 Competitors  
**Re:** Appendix 7

**Bulletin No:** GT4-05  
**Date:** 6 Apr 2024  
**Time:** 15:00

---

A report has been received from the Chief Timekeeper regarding RS1 Car #28. The report indicated the Driver switch was not functioning during Practice 2.


As it was not possible to assign the lap times achieved to a specific Driver the lap times are not valid. Thus, Car #28 has no recorded times for the session and must start at the back of the grid.



Scot Elkins  
Steward – Chairman



Coy Arbour  
Steward



Elliot Forbes Robinson  
Steward