

From: The Stewards
To: Competitor's Representative
#82 BimmerWorld

Decision No: GT4 - 04
Date: 11 July 2020
Time: 08:20

After the conclusion of GT4 SprintX Race 1, the Series Technical Delegate conducted inspections on podium and other random cars. The #82 car was found out of compliance on one measurement, and the Technical Delegate produced a Technical Infraction Acknowledgement form (#001) and conveyed that to the Stewards.

The Stewards reviewed the report, and interviewed the Technical Delegate. They also reviewed in-car video from the #82 car, particularly a clip of the car having a significant "off" early in the race.

Having considered the evidence, the Stewards issue a Team Reprimand to the #82 BimmerWorld team, and caution the team to carefully monitor their compliance.


Team: #82 Bimmerworld

Competition: GT4 SprintX Race 1

Facts: At Impound, excess camber was measured at the right rear wheel

Supporting Documents: Technical Infraction Acknowledgement form #001

Decision: Team Reprimand


John Walsh
Steward (Chairman)


Robert Davis
Steward


Peter Cunningham
Steward

Acknowledgement of Receipt:

Time:

Stewards Log No.	87	1052
Posted at:		
Date:	7/11/20 9:25	